

# Himachal Pradesh Public Works Department

## School Building Safety Certificate

No.

Dated;-

It is certified that the existing Building **Govt. Sen. Sec. <sup>School</sup> Dulehar**

**Tehsil Haroli Distt. Una** is having blocks (S) Floors (s) as per details below:-

Detail of Blocks (S) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)	Block (7)
No. of Floor (s) in the Block	2 Nos	3 Nos	1 No	2 Nos	1 No	1 No	NA

The building is owned/occupied by **Govt. Sen. Sec. Dulehar Tehsil Haroli Distt. Una** (*name of the Institution*) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the **Junior Engineer Dulehar Section HPPWD Haroli** on dated **04-10-2025** in the presence of mentioned School staff and that the building/premises seems fit for occupancy for running school with effect from ..... for a period of 5 Years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.

Issued on 04.10.2025 at HPPWD Sub Division Haroli.


Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail;-

*This Certificate is not meant for any legal purpose.*

  
Junior Engineer  
Dulehar Section  
HPPWD Haroli

  
Assistant Engineer  
HP,PWD Sub Division  
Tahliwal

  
Executive Engineer  
Haroli Division  
HPPWD Haroli

  
Principal,  
Govt. Model Senior Secondary School  
Dulehar, Distt. Una (H.P.)